Friday, 04/04/2008 9:22:09 AM

User: Julie Lecocq

Process Sheet

Drawing Name

Part Number

Drawing Number

Project Number

Customer

: CU-DAR001 Dart Helicopters Services

Job Number Estimate Number : 38399

P.O. Number

: 10006

This Issue

: NC

: 04/04/2008 S.O. No. :

First Issue

Prsht Rev.

: 38398

: //

Type

: LANDING GEAR

Previous Run Written By

Checked & Approved By

Comment

: Est Rev:A

05-10-25 New Issue

Total:

: B **Drawing Revision** Material

: 30/04/2008 **Due Date**

: FWD X-TUBE

: D2889 REV B

: D2889

: N/A

Qty:

1 Um:

Each

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

Description:

Crosstube material

D6005180 1.0

Comment: Qty.:

1.0000 Each(s)/Unit

1.0000 Each(s)

JLM

Crosstube material

D2889

Pick:

Qty Part number

Description Fwd Crosstube

Batch

8-4-8

2.0

BENDING

BENDING MACHINE - SKIDTUBES



Comment: LANDING GEAR RESOURCE 1

1-Bend D2889 as per Dwg D2889 and Folio FT001

3.0

SKIDTUBES 1

SKIDTUBESS RESOURCE



Comment: LANDING GEAR RESOURCE 1

1-Deburr and Polish

4.0 QC15

DIMENSIONAL CHECK OF X-TUBES



Comment: DIMENSIONAL CHECK OF X-TUBES

HAND FINISHING 5.0

Comment: HAND FINISHING RESOURCE #1

Acid etch and alodine as per QSI 005 4.1

Inside and outside of tube



ol







HAND FINISHING

Janu 6 1 37945

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #: Pault Category: NO	CR: Ye	s No DQ	A:	Date: _	
			QA:	N/C Close	d:	_ Date: _	

NCR:			WORK ORDE	ER NON-CONFORMAN	CE (NCR)						
DATE		Description of NC	Corrective Action Section B			Verification	Approval	Annessal			
	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	Approval QC Inspector			

NOTE: Date & initial all entries

Friday, 04/04/2008 9:22:09 AM Date: User: Julie Lecocq **Process Sheet** Drawing Name: FWD X-TUBE Customer: CU-DAR001 Dart Helicopters Services Part Number: D2889 Job Number: 38399 Job Number: Seq. #: **Machine Or Operation:** Description: INSPECT POWDER COAT/CHEMICAL CONVERSION 6.0 68/01 Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION A PACKAGING 1 7.0 Comment: PACKAGING RESOURCE #1 Identify and Stock Location: QC21 8.0 Comment: FINAL INSPECTION/W/O RELEASE Job Completion

Page 2

Form: rprocess

Dart Aerospace Ltd


W /O:		WORK ORDER	RCHANGES				
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspecto
Part No	:	PAR #: Fault Category:	NCR: Yes	No DQ	A:	Date: _	
			QA:	N/C Close	d:	Date: _	
NCR:		WORK ORDER NON-CO	NFORMANCE (NC	R)			

NCR:			WORK ORDE	ER NON-CONFORMAN	CE (NCR)						
		Corrective Action Section B		Verification App		Anneyel					
DATE	STEP	Description of NC Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector			

NOTE: Date & initial all entries

DART AEROSPACE LTD	Work Order:	38399
Description: Crosstube Fwd	Part Number:	D2889
Inspection Dwg: D2889 Rev: B		Page 1 of 1

Required Dimension	Min	Max
Height	49.875	50.125
1/2 Span	69.275	69.525
Angle	49	52
Total Span	138.55	139.05



Ç	omments	
* used on w/o	1 37945	
QC15 Inspection	۵, ,	
Date	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	7

Rev	Date	Change	Revised by	Apprø	ved
Α	07.02.06	New Issue	KJ/JM 🛠	p	~
			- ()		

